

**Name :-** DXB  
**Vehicle No :-** GO TEAM 1(DA-109)

**Company Name :-** DXB  
**Company Shift:-** Morning(08:00 to 08:00)



**WITH ENGINE is OFF CHECK THE FOLLOWING**

		<b>Select No For Damage/Others</b>	<b>Remark</b>
1	Kilometer at start of shift	10500	
2	Kilometer at end of shift	10600	
3	ENGINE LIGHTS INDICATOR WARNING	YES	
4	EXTERIOR OF VEHICLE CLEAN	YES	
5	INTERIOR OF VEHICLE CLEAN	YES	
6	WINDSHIELD WIPERS	YES	
7	SEAT BELT FUNCTIONS CORRECTLY	YES	
8	TIRE TREAD AND SIDEWALLS SHOW NO DAMAGE	NO	Worn off need to change







**TURN ON THE ENGINE CHECK THE FOLLOWING**

		<b>Select No For Damage/Others</b>	<b>Remark</b>
1	HEADLIGHTS FUNCTION ON BOTH HI AND LO BEAM	YES	
2	TURN SIGNALS FUNCTION (Left/Right)	YES	
3	BRAKE LIGHTS FUNCTION INCLUDING THIRD BRAKE LIGHT	YES	
4	FLUID LEAKS DISCOVERED	YES	
5	HORN SOUNDS	YES	
6	MIRRORS FUNCTION AND ARE CLEAN	YES	
7	EMERGENCY LIGHTS AND SIREN WORK	YES	
8	FLUID LIGHTS WORKING	YES	
9	BEACON LIGHTS WORKING	YES	
10	Vehicle Pass Valid	YES	
11	Specify Vehicle Fuel	YES	Full
12	Vehicle Equipment	YES	Additional phone given Samsung
13	ANY NEW DAMAGE NOTED PRIOR TO USING THIS VEHICLE?	YES	Yea small dent on driver door

**Others**

		<b>Select No For Damage/Others</b>	<b>Remark</b>
1	Specify the Tetra Number (1)	3089	
2	Specify the Tetra Number (2)	3067	
3	Specify the iPad number	6	
4	Specify the Tab Number	2	



**User Remark:**

Sent on right door